

ADDENDUM: LIMA 604

Disregard the placement of motor as described in Step 10. This placement is shown in error.

For proper placement and parts:

Step 8: Motor should be x4 pcs.

Step 10: Disregard step and motor placement.

To reconcile motor placement please see image below: Motors (x4) placed on surface brackets on underside cabin floor plate.

